

PLACE	DATE	TIME	SUMMARY OF EVENTS	REFERENCE TO APPENDICES
Camp Borden, Ont.	12-2-42	(Cont'd)	<p>Harvard 2647, piloted by Aus. 411539, LAC, Smith H.L. collided with Harvard 3184, piloted by R102779, LAC Danby, W.E., at 2020 hrs., during night circuits and landings at Edenvale Aerodrome. Neither pilot was injured. The collision was caused by pilot of aircraft 2647 failing to see aircraft 3184 stuck in snow in sufficient time to avoid skidding into it, after brakes had been applied and throttle back. Port Wing and Airscrew on Harvard were damaged beyond repair. Categorized as, Harvard 2647 - C.1, Harvard 3184-B.</p> <p>The monthly Mess Dinner was held in the Officers Mess. The Sr. M.O., Colonel Campbell, and a number of officers from the Army Medical Corps, Camp Borden were guests. Flying Officer Becket gave an illustrated lecture on the opening up of the interior of New Guinea.</p>	
	13-2-42		<p>Harvard 3164 damaged during night flying operations at 2150 hours, Edenvale Aerodrome Pilot, Pilot Officer D.C. Sutherland and Student Pilot Aus. 411741, LAC Byrne, A.E. were uninjured. Accident was caused by pilot failing to correct swing of aircraft in time. Aircrew and cowling were damaged. Categorized C.1/2.</p>	
	14-2-42		<p>Harvard 3160 force landed 0925 hrs. Stroud, Ontario. Pilot Aus. 411742, LAC, Campbell, K.G. was uninjured. Accident was caused while pilot was practicing forced landings by tail wheel striking furrow, forcing plane on its nose. Accident attributed to bad weather. Categorized C.1/2.</p>	