

4

15. However, as previously stated, we accepted the certification of an experienced, qualified engineer insofar as AWD 50-9 was concerned. His experience and previous dealings with us gave us no reason whatever to doubt his inspection and certification, although it later evolved that the inspection had not been carried out and the certification had been made in spite of this.


for Regional Director, Air Services