

- 2 -

Sunday evening Republic Seabee, CF-DKC was moored at our Temagami dock. It was checked at approximately 9 o'clock and everything was in order. During the night a coating of ice formed on the bay and apparently opened a seam in the main hull. Monday morning the aircraft has overturned, and only the starboard wing was above water. Within three hours we had hoisted the aircraft and pumped the hull. There was very little damage incurred in the lifting of the aircraft, but the tail section was slightly damaged in the capsizing, as well as the windows. Mr. Stirk dismantled the aircraft and transported it to his Orillia shop the following day.

After freeze-up we will examine CF-DSC more thoroughly and advise if it is to be repaired.

Yours very truly,

R.G. Simms, President,
LAKELAND AIRWAYS LIMITED.