

" " Bushings.....	0.8	0.10	0.12	0.14	0.18	0.35	0.50	0.65
Brass Bushings	0.8	0.10	0.12	0.14	0.19	0.35	0.50	0.65

MALLEABLE IRON FITTINGS.

ELBOWS.



Smooth without bead for Gas. With bead for Steam and Water.

No.		No.	
1.	$\frac{1}{2}$	25.	$\frac{1}{2} \times \frac{3}{4}$
2.	$\frac{1}{2} \times \frac{1}{5}$	26.	$\frac{1}{2} \times 1$
3.	$\frac{1}{4}$	27.	$\frac{1}{2} \times 1\frac{1}{2}$
4.	$\frac{3}{8} \times \frac{1}{5}$	28.	$1\frac{1}{2}$
5.	$\frac{3}{8} \times \frac{1}{2}$	31.	$2 \times 1\frac{1}{2}$
6.	$\frac{3}{8}$	32.	$2 \times 1\frac{1}{2}$
8.	$\frac{1}{2} \times \frac{3}{8}$	33.	2
9.	$\frac{1}{2}$	37.	$2\frac{1}{2} \times 2$
11.	$\frac{3}{4} \times \frac{3}{4}$	38.	$2\frac{1}{2}$
12.	$\frac{3}{4} \times \frac{1}{2}$	40.	3×2
13.	$\frac{1}{4}$	41.	$3 \times 2\frac{1}{2}$
16.	$1 \times \frac{1}{2}$	42.	3
17.	$1 \times \frac{3}{4}$	45.	$3\frac{1}{2} \times 3$
18.	1	46.	$3\frac{1}{2}$
21.	$1\frac{1}{4} \times \frac{3}{4}$	49.	$4 \times 3\frac{1}{2}$
22.	$1\frac{1}{4} \quad 1$	50.	4
23.	$1\frac{1}{4}$		