

COPY

17

WORK AND EXAMINATION REPORT OF CESSNA CRANE T50 AIRCRAFT CF BMM  
(RCAF #7989)

Aircraft examined in detail as to condition and functioning of all components.

Several small ringworms in the covering removed. R.C.A.F. markings removed. complete aircraft given a new coat of dope and registration letters affixed.

Both engines examined for internal corrosion and given a complete service.

Propellers removed to examine crankshafts for corrosion.

Engine mounts and installations examined.

All service work on this aircraft and engines was carried out by R.C.A.F. personnel under the supervision of F/L Gardner, Engineering Officer #10 RD Calgary.

Aircraft and engine log books examined and found in good order.

Record of Aircraft and Engine times submitted to the District Inspector, Air Regulations, Edmonton.

Duplicate copies of Form A1-6 issue 3 attached.

S. N. Green  
Air Engineer D

Feb. 16, 1946.