

-2-

T. W. Siers Esq.

March 11th, 1947.

The total engine time since overhaul is 135 hours 24 mins.

Attached are two copies of engine failure data report; it would be appreciated if one completed copy is returned after the engine has been dismantled and inspected.

The engine will be shipped to Canadian Pratt & Whitney for overhaul and inspection after Mr. Schweitzer completed his examination.

A. E. HUTT,
Superintendent of Maintenance,
Western Region.

Attach.

cc. E.R.R. Field Esq.
R. Carter Guest, Esq. D.I.A.R. Vancouver
K.F. Saunders Esq., D.O.T., Edmonton.