

CANADIAN AGRICULTURAL MACHINERY.

Plate 2.




Fig. 3.
Method of
Driving Mowers
through Pawls
in the Wheels.

Two leading methods of attaching the
Connecting-rod to the Knife.




Fig. 4.





Fig. 6.
Sectional End View,
showing the Adjustable
Brace, Tilting Lever, Hand
and Foot Spring Lift
and Underdraft.

Adjustable Brace.

Fig. 5.



Tempered Steel
Wearing
Plates

Plate 2.
Mechanical
Engineers 1901.