

4. A residence for the caretaker is absolutely necessary. We are at present paying rent for a house at some distance from the building, and there is no one on the premises at night.

5. The Boys' and Girls' Model Schools, which are of much importance in the training of teachers, now require all the space occupied by the Normal School classes, for which new and more suitable rooms should be provided.

6. The present work-shop connected with the Model Schools can only be regarded as a temporary and insufficient provision to meet a demand which daily grows more imperative.

7. The Building occupied by the Primary School is insufficient. It requires a room to accommodate 50 additional pupils of its grade, in order that it may be a proper feeder to the higher departments. For the purpose of training teachers, two small classrooms, of the capacity of 25 pupils each, should be added to this school. The teachers of the Primary School should have a retiring room.

8. A Kindergarten for 50 pupils should be added to this department, to afford to teachers-in-training opportunity of studying the best methods of instructing the smallest children. This would require the addition of two large rooms, with a hall, cloak room and other conveniences.

It has been ascertained that an addition to the present building, extending across the play-ground, could be very conveniently made, and would afford the necessary space for extension of the Normal School, for the Primary School, the Kindergarten, the Workshop and the Caretaker's residence, as well as for additional closets, cloak-rooms, &c., and for the Library and Apparatus.

Plans for such a building have been prepared by the Architect appointed by the Government, and have been carefully considered and approved by the Committee and Principal of the School, and they are of such a character as to give sufficient accommodation for many years.