



STUCKA FALLS OFFICE

The Resident Engineer and his staff of assistants are located here, the office building being within a few hundred feet of the works. The wing to the right of the photograph is a large draughting room. Cement testing and other laboratory work is provided for in the cellar. A Director's meeting room is in the second story of the tower. Bond & Smith, Architects.