

permitted to introduce into the mine any stranger or person employed by them, on any pretence, without the consent of the owner or manager.

166. Miners, and all other persons who shall have occasion to pass through any trap door, shall thereupon closely shut the same, and shall on no account leave it open. On discontinuing work at the end of a shift, and especially when no work is to be done in the mine the following day, care must be taken by every workman to closely shut all trap doors, so as to prevent the proper current of air necessary for ventilation from being diverted.

167. All workmen are prohibited from entering or remaining in any place throughout the whole mine where not absolutely required by duty to be at the time.

168. Miners and all other persons, except drivers and rope riders, are expressly forbidden to ride on loaded cars in or about any part of the mine.

169. Miners and all other persons are prohibited from defacing or removing marks which may be made on any part of the workings for the guidance of the workmen in their operations. All workmen are forbidden to displace, injure or damage in any way, the props, cars, rails, or any part of the machinery, gearing and apparatus.

170. Persons employed shall not take or interfere with any lamps, tools, rails, cars, or in any other articles or things belonging to, or in use by, or in charge of, any other person for the purpose of his employment without permission.