

17. Nothing.
18. None.
19. Yes, shingles, building paper, windows, doors, lumber, nails from the Band Funds.
20. No good foundations.

## STONEY RESERVE

Report submitted by Edward Hunter, Director I.A.A.

1. (a) Nearly all houses on the reserve are of log construction.  
(b) Less than 10 are of lumber.  
(c) No other construction.
2. (a) Few have more than one room.  
(b) Three or four have 2 rooms.  
(c) One or two have three rooms.  
(d) One.  
(e) About ten have vegetable pits.  
(f)
3. (a) Only a few of the newly built homes have double floors.  
(b) As above.  
(c) 1. None.  
2. Scarcely any.  
3. A few have paper lined walls but it is paper of poor quality and, as the people have little or no experience, the general effect is unpleasant.  
(d) None of brick.  
(e) At one time most houses had shingle roofs but these roofs are practically worn out now.  
(f) None.  
(g) Over the old shingles some people have laid tar paper.  
(h) None.  
(i) Only a few.
4. About 25 families or individuals have no homes, possibly because of the lumber shortage.
5. Houses are of various sizes, 16' x 14', 20' x 16', 10' x 12'.
6. The windows vary according to the size of the house. In the 16' x 14' houses usually 3, in the larger 4, in the smallest 2, sometimes 3.
7. 8 square feet.
8. Approximately 8 to 10 people.
9. As above.
10. Almost every house on the reserve needs repair badly.
11. About half the houses on the reserve.
12. 100 or more.
13. Some houses no longer fit to live in; young people wish to become house-holders.
14. No.
15. Lumber.
16. Yes.
17. A little lumber, windows, shingles.
18. Logs, remaining lumber needed, nails, etc.
19. No.
20. Only two or three.