

STRANG, ANDREW :

Nixon's purveyorship, 492.

STRONACH, JOHN :

contract No. 1, 639.
No. 2, 641.
No. 4, 641.
South Pembina Branch telegraph, 642.

SUPPLIES :

See Contracts ; Engineering ; Fort Frances Lock ; Nixon's Purveyorship.

SURVEYS :

See Engineering.

SUTHERLAND, HUGH :

Fort Frances Lock, 330, 829.
alleged misconduct, 338, 342.

SUTHERLAND, JAMES :

Fort Frances Lock, 452, 578, 807.

SUTHERLAND, PETER :

Nixon's purveyorship, 447.
correction, 547.

SUTTON & THIRTKELL :

See Contract No. 4.

SUTTON & THOMPSON :

See Contract No. 4.

SUTTON, R. T. :

contract No. 4, 1032, 1069.
No. 15, 1040.

SYSTEM OF LETTING CONTRACTS :

MACDONALD, A. P.

wrong from beginning to end, 981.
especially a money deposit, 981.
how it works, 981.
lowest tender system relieves Government of responsibility, 984.
temptations to officials to give information, 981.
never got information prior to putting in tender, 985.
system induces speculative tenders, 985.
collusion amongst contractors, 985.
throws contracts into the hands of ignorant capitalists, 987.
large deposits impoverish contractor, 988.
bulk sum contracts not the proper principle, 988.
approves of schedules of quantities, 989.

TRUDEAU, T.

no record kept of time when tenders received, 994.
clerks instructed to attach envelopes, 994.
these instructions have been very partially carried out, 994.

GOODWIN, J.

reliable contractors better for the public, 1011.
schedule of prices better than bulk sum, 1012.

RYAN, H.

bulk sum system an advantage to contractor, 1239.
schedule prices no injustice to public, 1239.

FLEMING, N.

exact quantities desirable, not essential, 1377.
inaccuracies due to insufficient knowledge as to muskeg country, 1377.
strictly accurate quantities not very essential, 1378.
generally as to receiving and opening tenders, 1384.
practice of making calculation of cost before inviting tenders, 1407.
advice to Minister as to acceptance or otherwise of tenders generally verbal, 1408.
no recollection of embodying any estimate of work about to be let in a report, 1408.