

that of the winder. Then the plan of the tray is equal to its bottom surface, and the two elevations to a side and an end respectively. In the diagram, the plan is below XY , and the elevations are above. The three series of




FIG. 72.

curves in the elevation of an end indicate that the parts so represented are three distinct pieces. The parts of the tray are to be held together by twelve nails placed in a regular order. Their positions are shown by the dots in