

PLACE	DATE	TIME	SUMMARY OF EVENTS	REFERENCE TO APPENDICES
Camp Borden, Ontario	18-11-42		<p style="text-align: center;">Page 6.</p> <p>Harvard 3159 piloted by AUS417090 LAC Litchfield, G.H., second pilot AUS409942, LAC Madden; P., while on cross country, crashed near Listowel at 1200 hours, killing both occupants. Aircraft crashed into ground, cause obscure. Investigation ordered. Categorized A.</p>	
	19-11-42		<p>At 0800 hours C.A.V.U. Wind 200/10 M.P.H. Flying washed in at 0800 hours and washed out at 1745 hours. 2 hours dual, 7-3/4 hours solo. No night flying on account of fog and rain. Total flying time 142.15 hours.</p>	
	20-11-42		<p>Flying washed out, C-O, V-O. Rain and fog.</p>	
	21-11-42		<p>At 0800 C. 800 feet, V. U., gradually clearing, improving at 1300 hours C.A.V.U. Flying washed in at 1000 hours and out 1745 hours. Instructor instrument 0830 hours to 1000 hours. Dual flying 2 hrs, solo 5-3/4 hours. Night flying from 1900 hours to 2359 hours. Total flying time 373.50 hours.</p>	
	22-11-42		<p>Harvard 3217 piloted by R139343, LAC Harris, S.D., landed with wheels up at R-2 Alliston at 1350 hours. Pilot uninjured. Pilot claims motor cut out. Categorized C, possible B.</p> <p>At 1330 hours C.A.V.U. Flying washed in at 1330 hours and washed out at 1745 hours. 4-1/4 hours solo. Night flying from 1900 hours to 0030 hours. Total flying time 271.10 hours.</p>	
	23-11-42		<p>At 0800 hours C.A.V.U. Flying washed in at 0800 hours, out at 1730 hours. Solo 9-1/2 hours. Night flying from 1900 hours to 0315 hours. Total flying time 536.50 hours.</p>	
	24-11-42		<p>Harvard 2650 piloted by AUS414687, LAC Hume, D., groundlooped at Camp Borden during night flying at 2030 hours. Pilot uninjured. Caused by broken shear pin in steering post. Categorized C-1/2.</p> <p>C-O, V/O. All day and all night fog. Flying time nil.</p>	
	25-11-42		<p>0945 hours C. 1800 feet, V 4-5 miles. Fog slowly clearing. Dual only 6.55 hours. No night flying. Total flying time 277.30 hours.</p>	

