

IRON, GAS AND STEAM PIPE, AND FITTINGS.

SIZE OF BORE.	$\frac{1}{4}$	$\frac{3}{8}$	$\frac{1}{2}$	$\frac{3}{4}$	1	$1\frac{1}{2}$	2	$2\frac{1}{2}$	3	$3\frac{1}{2}$	4 inch.
Iron Pipe.....	\$ c. 0.6	\$ c. 0.7	\$ c. 0.8	\$ c. 0.12	\$ c. 0.16	\$ c. 0.22	\$ c. 0.28	\$ c. 0.42	\$ c. 0.78	\$ c. 1.10	\$ c. 1.38
Wrought Iron Couplings.....	0.5	0.6	0.9	0.10	0.12	0.18	0.21	0.36			
Nipples	0.6	0.6	0.9	0.11	0.12	0.18	0.24	0.36			
Bends.....	0.20	0.21	0.24	0.33	0.45	0.63	0.80	1.53			
Flanges, Wrought Iron.....	0.27	0.30	0.36	0.42	0.48	0.54	0.63	0.90	1.80	3.10	3.60
Iron Main Coos.....	0.55	0.65	0.85	1.10	1.55	2.05	2.70	4.40	6.25	9.00	14.50
Malleable Iron Unions.....	0.22	0.30	0.40	0.50	0.65	0.95	1.20	1.80	2.50	3.25	
" " Bushings.....	0.8	0.10	0.12	0.14	0.19	0.35	0.50	0.65			
Brass Bushings	0.8	0.10	0.12	0.14	0.19	0.35	0.50	0.65			