

TMS/20

Ottawa, February 13th, 1946. 16

L-445


Cessna T50 aircraft CF-BMM

5008-B13-13

AIR MAIL

District Inspector, Air Regulations,
402 Blowey-Henry Bldg.,
Edmonton, Alta.

1. With reference to your letter of the 19th ultimo enclosing application for Certificate of Registration and Certificate of Airworthiness for the above-noted aircraft in the name of Donald Revie, Cranbrook, B.C., it is noted under Paragraph 2 that you state aircraft and engines were inspected by 'B' and 'D' Air Engineer Stan Green in accordance with Information Circular No. T/22/38.
2. Will you kindly advise what action Air Engineer Green took to ensure that the requirements of Addendum No. 1 to Information Circular No. T/22/38 have been complied with. This refers to Paragraphs 3 and 4 as it is noted that the engines have a total service life of 105 hours 35 minutes since last complete overhaul and were kept in storage beyond sixty days.
3. Kindly treat this matter as urgent.


(S. Graham),
Superintendent, Air Regulations.

c.c. D.I.A.R. VANCOUVER 