

12

ENGINE FAILURES AND UNSCHEDULED REMOVALS

Date JUNE 25, 1959.

Regional Aircraft Inspector
Room 36, Trans-Atlantic Bldg.
Montreal Airport, Que.

Engine installed in aircraft CF-ALL Type BEECH F105

Date of Failure JUNE 25, 1959.

Engine Type and Model P&W R985-AN14B

Engine Serial Number JP 210530

Total Time Since New UNKNOWN.


Total Time since Overhaul 153:45

Last Overhaul by EIGHTH AIR DEPOT, SEBRING, FLORIDA.

Engine will be overhauled by CANADIAN PRATT & WHITNEY

Reason for failure SUPERCHARGER BEARING FAILURE.

MICARTA FOUND IN MAIN SUMP. FLAKING AND
CHIPPINGS FOUND IN MAIN SCREEN. HIGH OIL
CONSUMPTION, CONSISTENT OIL RESIDUE IN INDUCTION
SYSTEM.


(*Finnius Aviation Limited*)
Engineer's signature
ULM89