

C
O
P
Y

39

May 13, 1950.

P.O. Box 71
Sioux Lookout, Ontario.

Inspector of Air Regulations,
Dominion Public Bldg.,
Winnipeg, Man.

Dear Sir:

Subject Moth CF-CTI

For your information and files.

On May 7th, 1950, while flying out of Osnaburgh House Lake St. Joseph, the writer had the misfortune to have an engine failure on the above mentioned aircraft and was forced to put the aircraft into the bush, causing damage to both port wings. Cause of failure was found to be excessive water in the gas, due to not using a chamois, which could not be located.

The aircraft will be left in its present location till such time as weather and time permits moving it.

Hoping this meets with your requirements.

Yours truly,

"E.S. Richards"

P.S. The pilot suffered no ill effects.