						•		•	-		
Aug.	I.—To	paid working at Sir Gaspard,	`		•						
•		and making house for do.	· <b>5</b>	11	$7\frac{1}{2}$	,		-		*	
		Working at cars,		15	0		٠,	•	*		,
t.	1					7	6	7			
<i>"</i>	8.	Working at engine Sir Gaspard,	7	- 0	6	,	-	- 4			
•		Making patterns for en. Mayfl'r.		15	0						
		Working at cars,	9.	12	6	,			٠,		
_	,		0	3	9		•	χ.	,		
		Working at engine J. Howe,	U	Ð	J	10	17	Ω			
	· •	TOTAL TOTAL		10		16	11	3	`		٠,
1	<b>15.</b>	Working at engine J. Howe,		10							
•		" at engine Sir Gaspard,	1	15	O)	-					
1		" at cars, and repairing			٠.						
, ~		break rods,	<b>2</b>	16	6	,					
		Making rings and staples for	-		•	•		~			
-	′ .*	horse cars,	0	9.	. 0	•	•	1.4			-
		· -				5	10	6			
•	29	Working at engine Sir Gaspard,	0	17	6			,			
	,	" at engine J. Howe,	•	_,	·						
		and making cow catcher,	9	1	6						٠,
,		and making cow. catcher,	<b>"</b>	` .	Ų	. 9	19	æ	1		
,	60	TT T	<u> </u>	0		. 2	19	0			-
	29.	Working at cars,	. 4	3	9	-	1				,
	, 4	Making cow catcher, and			•	•	`				
`		mending bonnet for en-	_	_	•_					-	
	•	gine J. Howe,	2	4	3		,	-	•		
•	4	Working at carriages, omit-					`			,	
	r	ted last week,	1	13	$\mathfrak{d}$		•				
de,		Working at tender for Sir				,			,		٠.
1 /		Gaspard engine,	0	7	6	*		• .	•	,	
••,		<b>.</b>				6	12	`3		٠.	
Sont	5To	paid working at carriages,	1	5	O	~	-		33	0	14
ect.	0.—10	Making cow catcher for		Ŭ	, •	~			90	U	-2
_	,	Joseph Howe engine,	9	11	0	Ę					<del>-</del> -
	•			17	6		· .	7			•
•		Working at Sir Gaspard engine,	U	, T.	U	×	19	œ	1	T 1-	
	1.0	TITLE TO THE TAXABLE		<del></del>		٠. 4	19	6	•		`
	13.	Working at engine J. Howe, and		-	^		- 21			•	
		making cow catcher,	3	7	U		-			¹ #	
		Cleaning wheels for engine May-	_					,		. ;	
	,	flower,	0	5	0	ţ		o			
,		Working at carriages,	1	2	· 6				,	^	
•	, 4		<u> </u>			4	14	6	, !		3
	20.	Working at carriages,	2	12	0	•		,		, t	1 1
1 4	•	Making patterns for cars,		15	0	` _ `	•	•		- C	
1	, - ,	Working at Sir Gaspard engine,		17	6			*	•		
		at cow catcher, for	٠		•						
		engine Joseph Hewe,	2	2	0	6	6	6			
		engine soseph Hewe,							15	14	6
	97	Working at anging T Uswa	^	10	0				TO	7.7	U
	27.	Working at engine J. Howe,									
•		" at engine Mayflower,		17	6						
		Fitting iron patterns,	_	10	0						
		Working at engine Sir Gaspard,	0	3	9						
		" at cars, and making	_	• -	_						
		stakes for do.	2	16	3						
		Working at cow catcher for									
		engine Joseph Howe,	1	5	0	6	2	6			
• ••									6	2	6