


Fig 2



WOOL-CARDING MACHINERY.




FIG 1.




FIG. 2.



FIG. 3.



FIG 4.

FIG. 5.

SCHMITZ'S REVOLVING FIRE-BARS.