


Brass Workers' Machinery.
(Send for Circulars.)



2-Spindle Valve Milling Machine	\$325 00
Fox Lathe, complete.	360 00
Fox Monitor Lathe, complete.	450 00
Cock Grinding Lathe, "	140 00
Plain Lathe, with set over tail stock	200 00
8-in. Bench Lathe and C shaft	75 00
12 " Plain " " " (on legs)	110 00
14 " " " " " "	135 00
12 and 14-in. Lathes, with compound tool rest, extra	35 00
Globe Valve Chuck, to 1 inch	60 00
" " " " " "	70 00

(For Brass Monitors see Turret Lathes.)

No. 4.
4½.
5.
6.
6.
7.
1.
1.
2.

No 1.
2.
2.
6.
7.
Foot Po
Circular
Combini
clue
Att
Chu
Combini
and
Circular
Cro
Scroll S

WI
Machin
furnish
followi
Circular
Circ
Scroll S
Boring
Drill
Counter