

## MEMORANDUM.

Department of Indian Affairs,

To

Ottawa,

18

occurs in the first line of the Description S. E.  $\frac{1}{4}$ . should be S. W.  $\frac{1}{4}$ .

also, there is an error of 3 feet in the total length of the Centre Line across the said Section in the Description, the same distance as shown between the stations on the Plan is 3 feet shorter.

*min*  
The survey of ~~the~~ these lands are situated within the Railway Belt, the survey should in order to be legal must be performed by a Dominion Land Surveyor also the Plans must be signed by him. It is not necessary that copies of the original Plans that may be required be signed by the Surveyor himself, but the Dept. requires, in addition to the signature of the President or other officer representing the Railway Company, that <sup>the date of survey and</sup> a copy of the Surveyor's signature be placed, in the usual manner, on each plan submitted.

*W.C.*

*James D. [unclear]*