

effective work will be lessened. The real work performed, however, will be the same whether the friction be much or little, as it requires an expenditure of energy to overcome friction. And the measure of the energy expended is found in the heat which the friction produces.