PLACE	DATE	TIME	SUMMARY OF EVENTS	REFERENC TO APPENDIC
Camp Borden, Ont	3-2-42	(Cont'd)	Harvard 2968 damaged at Edenvale Aerodrome at 1945 hrs. The pilot Aus. 411798, LAC Mill-	Marine .
		12	ingen, I.L. was uninjured. The accident which took place while pilot was making night	
			circuits and landings was caused by pilot failing to make complete cockpit drill before	
		10.00	landing and as a result undercarriage was left retracted; warning horn sounded on throt-	1
		-	tling back; pilot opened throttle but airscrew tips struck ground, circuit was completed	
			and normal landing made. Categorized C.1.	
	4-2-42	a faith and a start	NIL	P
	5-2-42		Mr. Brown, Canadian Wright Ltd., representative, visited the Station, investigating	
		1.1	trouble inWright Aircraft Engines.	
		1893944 ·····	Assistant Section Officers V 36007, J.G. Cumming and V 30005, W. Walker, visited the	
			Station to discuss plans for the posting of C.W.A.A.F. to No. 1 S.F.T.S.	
	6-2-42		Wing Commander Kent, D.F.C., H.F.C., RAF (Operational Fighter Pilot) visited the Station	
	1		and gave a lecture in the theatre to Station Personnel.	
	7-2-42	1997 - 19	Hon. Flight Lieutenant C 3572 B. Miller (SR) (Chap) reported on temporary duty from	
			No. 1 M.D. Toronto, to conduct the Protestant Services on the Station on Sunday.	
	8-2-42		NIL	
	•	1	· · · · · · · · · · · · · · · · · · ·	0
				140 . 35

....

*

-