

120292/5


Ottawa, July 26, 1911.

Rev. Sir,

The attention of the Department has been called by Mr. Inspector Green in his report on the Coqualactsa Industrial School to the laundry in the basement, which he states is in poor condition. The tubs have been so long in use that they have a peculiar and very unpleasant smell, the ceiling is low, the plumbing is not satisfactory as at present the dirty water instead of being carried off runs over the floor, the light and ventilation are bad and the laundry is said to be unhealthy. I trust that you will have the necessary action taken to improve the conditions there.

The Inspector also reports that he considers that two hydrants should be placed one in front of the main building and one at the back between the house and out-buildings for further fire protection.

Your obedient servant,

  
Asst. Deputy and Secretary.

Rev. T. Ferrier,  
Supt. Methodist Indian Schools,  
Brandon, Man.

Dept. of Indian & Northern Affairs. Letterbook.  
10 June 1911 - 26 July 1911. (RG 10, Volume 5354)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA