PRODUCTION SERVICES

This unit does reproduction work for all divisions of the Department. Because of the type work, packing and storage areas are required and should be located on the ground or sub-basement floor level.

Loading requirements for the storage area should be in the 250 lbs./sq. ft. region if located on the first floor. If on grade, then this factor can be reduced.

Design for floor in the working areas should be similarly designed.

Function	Staff	Area	Remarks
Officer	1	150	P.O.
Staff	4	570	G.O. including reception area and counter.
Composing Section			
Proof Reading	•	180	G.O. with S.P. @ 90.
Typing Pool	7	825	G. O.
Varitype	4	550	G.O. to include sink.
Production Section			
Supervisor	1	120	S.P.
Xerox	3	370	G.O.
Adheograph	2	380	G.O.
Photostat	2	600	G.O. 1 photostat at 215. 1 headliner @ 30 1 duplicator @ 60 3 compartment s/s sink. 30" x 24" x 8" exhaust fan. store room @ 100.
Multilith	5	1,810	G.O. Space for 6 machines @ 300. Area required for large deep sink for cleaning plates. Electric knife @ 200
			Electric drill @ 100 Slacker @ 100 Stapler @ 100.
Collating and Binding	5	1,850	G.O. automatic collator including work areas in area of 50 x 20.
Mail	1	300	G.O.
Secure Storage		120	Fire door.