

29

6. The cockpit was completely demolished and the inspector was informed by the Coroner that the body was found on the ground at the base of the tree directly below the demolished cockpit, still strapped to portions of the seat.
7. There was no evidence to be found that the aircraft had come in contact with the ground at any time prior to striking the tree.
8. The aircraft was then inspected by Inspector D. Bell and then released for removal.
9. There were no witnesses found to the actual crash, however, one witness was found who had observed its flight up to a few seconds prior to the crash who's statement was received and is attached.
10. Inspectors Place and Bell then returned to Toronto.

R.W. Place

(R.W. Place),
Inspector, Civil Aviation.

RWP/fs
Attach.