

however, still deficient in many respects, and it is my most earnest desire that such defects and deficiencies as it has, should be as soon as possible removed. That they may be so, I append a list of those which seem to me to most need attention.

(1) The windows of the main Asylum should be overhauled and repaired upon some system that would make escape through them more difficult than it is at present; and that would at the same time make them more efficient as ventilators than they now are.

(2) I desire again to recommend that the Asylum be provided with an auxiliary well and pump, as we are at present in danger of being left without water at any time, without a moment's notice.

(3) For several reasons we ought to have a separate building for religious purposes.

(4) A coal shed is required at the west cottage, similar to the sheds provided for the north and east cottages.

(5) We want a second wagonette.

(6) We want tea and coffee urns for the women's dining-room in the main Asylum, similar to those bought some years ago for the men's dining-room.

(7) The flooring of the main Asylum with hardwood ought to be gone on with.

(8) We want a hay shed built between the two barns.

(9) We require a new steam boiler in place of one which has been used for eleven years, and which is no longer safe. Another boiler requires overhauling and thorough repairing.

(10) The roof of the wings of the main Asylum leaks. The slate should be taken off and re-laid upon felting, as was done a few years ago in the case of the centre building.