



Fig. 3.



32606 O'Connor's Metallic Buckle, etc.



32607 Lee's Cart Seat.

Fig. 1.




Fig. 2.




Fig. 3.






Fig. 4.



32608 Jones' Cap for Oil Cups, etc.



32609 Deadman's Snow Plough.

Fig. 1.







Fig. 2.




32610 Connelly's Machine for Carding Cotton.




32611 Rizer's Machine for Watering Lands.



32612 Lee's Anti-Rattler for Thill Couplings.



32613 Rogers' Die for Swaging Drive Screws.



32614 Rogers' Mode of Forming Screw Threads.