

ILLUSTRATIONS

Photographs.

	PAGE.
Plate I. Turtle mountain, near Frank, Alberta.....	FRONTISPIECE.
" II. Looking south over Frank to 1903 slide. The 'contorted zones' in the limestone at the base of the 'North Peak Block' appear above the smokestack of the Power House	14
" III. Profile view of the north shoulder of Turtle mountain, directly above the town of Frank.....	14
" IV. Photographs of model illustrating the topography and structure of Turtle mountain.....	14
" V. Looking northward, along one of the larger fissures in the limestone on Turtle mountain. The limestone on the right has slipped down fifteen or more feet. The fissuring and slipping (faulting) were clearly facilitated by the joint-planes, some of which appear in the photograph. The North peak is seen in the upper right-hand corner	16
" VI. Looking north along a main fissure between the North and South peaks. The trees show strong movement of the limestone block on the right of the fissure..	16
" VII. Looking north to the North peak along a main fissure which is exposed for 1,500 feet.....	16
" VIII. Looking north to North peak over the fissured area..	16
" IX. View of the fissured area looking north from South peak	16
" X. Detail of a main fissure in the limestone.....	16
" XI. A main fissure produced, like the others shown in previous plates, by the pull exerted on the mountain top during the 1903 slide.....	16
" XII. A part of the fissured area taken with a levelled camera. The movement of the limestone in 1903 is indicated by the attitude of the trees.....	16
" XIII. View of Turtle mountain before 1903 slide from a point 3,100 feet northeast of the smelter building.....	18
" XIV. View of Turtle mountain in October, 1911, taken from the same point as Plate XIII. The block which broke away in the 1903 slide is shown in outline.	18
" XV. View of Turtle mountain before the slide of 1903, taken from the bluff two hundred yards east of the railway station	18
" XVI. View of Turtle mountain in October, 1911, taken from the same point as Plate XV.....	18
" XVII. View of lower part of area devastated in 1903, taken from north spur of Turtle mountain. This photograph illustrates the formation of terminal lobes produced by the 'splaying' of the material in a great landslide	24