

is the belt is made up in plies as for ordinary use and finished off on one side with a 1-16 or $\frac{1}{8}$ inch face of solid rubber to provide a wearing surface for carrying the material.




FIG. 2.

Belts for carrying grain are sometimes made in the same way although the standard grain conveyor belt is not provided with a heavy rubber carrying face