


Sundry Iron-Working Machinery.

EXTRA PER
FOOT OF BED.

	\$15 00
	20 00
	20 00
	25 00
.....	\$400 00
.....	450 00
.....	525 00
and	
.....	650 00
.....	\$350 00
.....	400 00
.....	450 00
.....	550 00

E OF FEED.

& power.	
"	
"	
"	
"	
.....	\$140 00
.....	190 00
.....	1,200 00



I will mail, on application, circulars giving full description of any of the following machines. Where I have no circulars I can generally send photos and a letter-press description.

Punch and Shears, 6 in. gap, "Single"	\$200 00
" " 12 " " "	320 00
" " 24 " " "	450 00
" " 12 " " "Double"	500 00
" " 24 " " "	725 00
Bradley Hammer, 40 lb.	400 00
Drop Hammer, 500 " Moline Pattern	500 00
" " 800 " P. and W. "	800 00
Drop Press, No. 19, Bliss "	225 00
" " Heavy " "	350 00
Bolt Cutter, Stationary Die, Cuts from $\frac{3}{8}$ to $1\frac{1}{2}$ inches, with Taps, Dies and Collets	350 00
Bolt Cutter A. and P. revolving head, Cuts from $\frac{3}{8}$ to $1\frac{1}{2}$ inches	380 00
" Schlenger " "	425 00
Seaton Bolt Headers, No. 1 Machine	800 00
" " 2 " "	1,000 00
" " 3 " "	1,400 00
Forge Furnace, 26x34 inside, lined with fire brick	75 00
Key Seat Slotters, $\frac{3}{8}$, $\frac{1}{2}$ and $\frac{3}{4}$ -inch cutters	125 00
Heavy Slotting Machine	1,100 00
Index Centres for Milling Machine	140 00