

FWC/33

OTTAWA, Ontario. October 9th, 1946.

Douglas DC-3 CF-ECN
P & W RL830-92 Engine No. 108483

5008 -E3-14

District Inspector Air Regulations,
402 Blouey-Henry Building,
EDMONTON, Alberta.

Attention: Resident Inspector A.I.D.

1. Further to our letter dated September 17th and co-related correspondence on the failure of No. 11 Induction Port Insert of the subject engine.

2. We are in receipt of a copy of the inspection report from Canadian Pratt & Whitney Aircraft Company, Limited addressed to McInnes Products Corporation, dated September 9th, 1946; copy of which is herewith enclosed for your information. We also enclose copy of a letter from the company dated September 24th, 1946 which contains, in paragraph 3, information regarding the Service Bulletin we referred to in our letter to you dated September 17th, 1946.

JL.

(J. L. Smith),
Acting Chief, Aeronautical Engineer.

Encl. 2

24