

PLACE	DATE	TIME	SUMMARY OF EVENTS	REFERENCE TO APPENDICES
Camp Borden, Ontario	9-11-42		<p style="text-align: center;">Page 4.</p> <p>At 0800 hours C.A.V.U. becoming hazy around 1100 hours with decreasing visibility in the P.M. and overcast. 5 hours dual, 5 hours solo. Flying washed in at 0800 hours and out at 1800. No night flying. Total flying time 262.40 hours.</p> <p>Harvard 2639 piloted by R157457, LAC Finch, turned over near Mount Forest at 1200 hours. Pilot uninjured. Pilot became lost, attempted forced landing after running out of gas, turned over. Categorized B.</p> <p>Harvard II 3311 piloted by AUS417075, LAC Evans, B.P. hit fence on landing near Shelbourne at 1147 hours. Pilot uninjured, became lost on cross-country and failed to make a precautionary landing without damage to aircraft. Categorized B.</p>	
	10-11-42		<p>Women's Division held second meeting of Handicraft Group.</p> <p>At 0800 hours heavy rain, breaking up in the P.M. High wind starting 1300 hours. 7 hours dual only. Flying washed in at 0930 hours, washed out at 1630 hours. Total flying time 200.45 hours.</p>	
	11-11-42		<p>Winter weather, some snow. Flying washed in at 0900 hours, washed out at 1030 hours. Washed in at 1330 hours, washed out 1615 hours. 4-1/4 hours dual only. Total flying time 196.55 hours.</p>	
	12-11-42		<p>Women's Division held second meeting of Discussion Group.</p> <p>At 0800 hours C.A.V.U. but snow to N. and E. Forecast snow in P.M. Flying washed out at 1500 hours. 1-3/4 hours dual, 5-1/4 hours solo. Total flying time 291.50 hours.</p> <p>Harvard 3169 collided with rear of Yale 3393 at main aerodrome at 1140 hours. Harvard piloted by P/O T.W. Wann (J13348), Student Pilot GB568875, Cpl. Smith, J.K. Yale piloted by F/O A. Hunter (J10097), Student Pilot GB 957151, Cpl. Coker, A.F. All occupants uninjured. Pilot of Harvard failed to keep checking landing path. Categorized Harvard C2, Yale B.</p> <p>Harvard FE-465 piloted by P/O S.S. Mitchell (J8929), Student Pilot R15377 LAC Faught, J.E., turned over on main aerodrome at 1100 hours. Aircraft overshot runway and turned over on its back. Occupants uninjured. Categorized C2.</p>	