


| PLACE                | DATE    | TIME | SUMMARY OF EVENTS   | REFERENCE TO APPENDICES   |
|----------------------|---------|------|---|---|
| Camp Borden, Ontario | 22-2-43 |      | <p>0700 C.A.V.U. Dual. Flying washed in at 0645 hours, washed out 1530 hours. 7<math>\frac{3}{4}</math> hours dual, 1 hour solo - 8<math>\frac{3}{4}</math> hours. Flying time 396.05.</p> <p>Harvard 2816 while taxiing to avoid other aircraft on Main Aerodrome collided with Harvard 2965. The pilot of Harvard 2816, Flying Officer R.E. Henderson, J10278, and student, R164080 LAC Clarke, G.W., were uninjured. The Pilot of Harvard 2965, Flying Officer L. Sykes, J10308 and student, R156984 LAC Kubicki, W. were uninjured. Harvard 2816 was categorized C1 and Harvard 2965 was categorized C4. The accident occurred at approximately 0850 hours.</p> |   |
|                      | 23-2-43 |      | <p>0630 hours C 4000 feet, V - 5 miles. Wind 180/2. Dual. Flying washed in 0700 hours, washed out 1200 hours. Dual only - 5 hours. Flying time 320.20 hours.</p>  |   |
|                      | 24-2-43 |      | <p>0800 hours Ceiling 1000 feet, V - 2 miles. Aerodrome unserviceable. Flying washed in 1330 hours, washed out 1800 hours. 3 aircraft per flight. 4<math>\frac{1}{2}</math> hours dual only. Flying time 208.45 hours.</p>  |   |
|                      | 25-2-43 |      | <p>0700 hours C.A.V.U. Wind 020/5. Flying washed in at 0700 hours, washed out 1700 hours. 3 hours dual, 7 hours solo. Total 10 hours. Night flying 2000 to 2200 hours. Flying time 513.30 hours.</p>  |   |
|                      | 26-2-43 |      | <p>0800 C.A.V.U. Wind 180/10. Snow coming on. Flying washed in at 0815 hours, washed out 1030 hours. 2<math>\frac{1}{4}</math> hours dual only. Flying time 46.25 hours.</p>  |   |
|                      | 27-2-43 |      | <p>0800 C.A.V.U. Wind 290/5. Snow to North. Dual 0900 hours. Solo washed in 0815 hours, washed out 1800 hours. 2 hours dual, 7<math>\frac{3}{4}</math> hours solo. Total 9<math>\frac{3}{4}</math> hours. Night flying washed in 1945 hours, washed out 2105. Flying time 372.35 hours.</p>   |   |
|                      |         |      | <p>On take-off part of runway at R.1 Edenvale Harvard B W 202 and Harvard 3045 collided when getting positioned, one to take off and one to get back to hangar. The pilots, R144286 LAC Sloski, J.A. and R148645 LAC McConvey, C.J. were uninjured. The accident occurred at 1432 hours. Both aircraft categorized C1.</p> <p>At 1715 hours Harvard F.E. 465 hit moving gas truck while taxiing back to hangar at R.1 Edenvale. The pilot, R148890 LAC Macklem, P.G. and R134224 AC1 Strom, W.B. Driver Transport were uninjured. Categorized C1.</p>   |  |