
Rogers' Brazing Lamp.

FOR BAND SAWS UP TO 11/4 IN. WIDE,



WHEELS

MERY

Ш

ЦO

5

PRICE

REVISED

INCHES

THICKNESS IN

This machine does away with tongs, kinks, curved and defective brazes.

The two flames meeting at the saw produce great heat. Saws are heated in less than 30 seconds

Sent on 10 days' trial to responsible parties.

DIRECTIONS — File the laps ; place the saw on the form with back to the straight edge, and clamp in place by tightening thumb screws ; clean the silver solder with fine sand paper and acid ; also the laps ; place the solder in the lap ; use plenty of powdered borax ; light lamps, fill the rubber globe by blowing in mouthpiece, watch until the saw is a cherry red, then press down on the lever, when the clamps will seize the saw firmly and give it mper without any danger of checking or kinking the saw.

PRICE.....\$15.00

AT Send for Net Cash Price.