

Cloak rooms must be placed in proper relation to the class room and should be well lighted and ventilated.

The lighting of class rooms must be carefully designed so that the *standard* amount of glass area is provided in proportion to the room and in the *right* location in relation to the direction the pupils are to face.

An efficient heating system must be provided and carefully designed on practical lines to heat the building uniformly in the coldest weather, and in doing this care should be taken to secure competitive prices in order that the cost will not be excessive. *If one particular system is decided on by the exclusion of competitive systems, an exorbitant cost will probably be the result.*

A positive ventilation system must be provided to supply an *abundance of fresh air* at all times. Many of the so-called ventilation systems are useless.

Proper sanitary arrangements are advisable and it is absolutely necessary that these be not installed in any haphazard fashion.

The exterior should be pleasing and of good design and be an object lesson in art to the pupils and the public generally. This does not mean extravagant ornamentation or any additional expense, but only requires *expert design in accordance with approved architectural practice.*

There are many other features necessary to the first-class efficient school but space prohibits going into these at greater length. Sufficient to say that, *if plans are secured from competent registered architects, all details of construction and arrangement will be carefully provided for.*

The accompanying plans have been carefully selected from some fifty school buildings erected in Western Canada from the plans of *Storren and Van Eenouwl*, Architects of Regina, Saskatchewan who have made a specialty of school architecture. The arrangements shown are therefore *not experiments* but have been thoroughly tested by actual use and experience.

Further information or advice in reference to schools, costs of buildings illustrated herewith and scale of charges for plans, specifications, etc. will be furnished on request by *Storren and Van Eenouwl*, Architects, whose address is Suites 1013-14 McCallum-Hill Building, Regina, Saskatchewan.