




38714 Curtis' Method of Manufacturing Barbed Wire.




38715 Jones' Car Coupler.




38716 Dearth's Washing Machine.




38717 Simpson's Churn.




38718 Butterworth's Warm Air Furnace.




38720 Burdon's Compound Ingot and Wire made therefrom.



38721 Dinneen and Hagerty's Circular Knitting Machine.



38722 Rae's Electric Car Motor.



38723 Baker and Randall's Composition Material.