Novr. 1	Fo paid Feetham's return	n,	£11 10 9	
8.	- Do.	-	12 6 0	
14.	Do.	,	12 6 0	
22.	Do.		12  6  -0	
241	<b>D</b> 0.		14 0 0	48 8 9
28.	Do.		12 6 0	40 0 0
20.				
	Less revenue,		630	
				630
Decr 6'	Fo paid Feetham's retur		* - 11 19 9	
12.	Do.	ш,	9.15 0	
12.				,
	Do.			
26.	· Do.	· ·	<b>11 1</b> 9 9	
		-		$45 \ 16 \ 0$
	John Stairs,	'	8 1 6	
1	``````````````````````````````````````	`	$2^{-19}$ 0	
	-			11 0 6
			· ř	
'				E618 14 5%
			, <b>e</b>	VOID 11 02
-	CR.		1	
		- , `		
	By revenue,	•	-	C618 14 53
•	~	•		
		2	,	. ,
	•		· · · ·	,
			,	•

## [E.]

Plant and materials on hand.

RICHMOND STATION.

Machine, blacksmiths, and joiner's shops, wharves, sidings, loading banks, offices, storehouses, station sheds turnable, and a quantity of waggon timber and other timber, and iron castings on hand, &c. &c.

3 locomotives, 4 passenger carriages, 4 horse boxes, 2 freight vans, 13 platform waggons, 2 ballast waggons, 1 travelling crane, 2 hand cars.

5868 tons rails,

2755 tons iron chairs,

167 tons spikes,

222723 five inch keys,

59892 eight inch keys,

38 tons service rails,

36 setts switches and crossings.

The above includes the portion of rails, &c. laid down.

BEBFORD STATION.

Store and dwelling houses, Loading banks and sidings, &c. &c. &c. Offices in town, furnished.

23