

BRANCH TEES OR HEADERS.

	1 inch Branch Tees		1½ inch Branch Tees.	1½ inch Branch Tees	2 inch Branch Tees
	2½ in. n Centre to Centre		3 inch Centre to Centre	3½ inch Centre to Centre	4½ inch Centre to Centre
	2 inch Run	2½ in. Run	2½ inch Run	3 inch Run	3½ inch Run
2	\$1 15	\$	\$	\$	\$
3	1 35		2 40	3 80	6 25
4	1 60		2 85	4 60	7 75
5	1 85		3 55	5 50	9 25
6	2 10		3 95	6 25	10 75
7	2 45		4 20	7 25	13 00
8	2 75		4 95	7 75	14 00
9	3 40	4 30	6 15	9 00	15 00
10	4 00	5 00	6 85	10 00	16 50
11	4 80	5 50	7 25	10 75	
12	5 10	5 85	7 65	11 50	
13	6 00		8 25		
14	7 25		9 00		
15	7 25		9 75		
16	8 25		10 95		

NOTE.—All openings in branch tees for circulation are tapped right hand. Branch tees for box coils are always tapped left hand in branches, and right hand in back inlet.

HOOK AND RING PLATES.

Number of Branches	1	2	3	4	5	6	7	8	9	10	11	12
HOOK PLATES.												
1 in. pipe, 2½ in. centre to centre	c. 09	c. 18	c. 23	c. 26	\$ c. 32	\$ c. 38	\$ c. 48	\$ c. 59	\$ c. 65	\$ c. 75	\$ c. 85	\$ c. 1 00
1½ " 3 " "	10	21	27	32	41	52	68	80	90	1 00	1 35	1 40
1½ " 3½ " "	15	28	43	58	72	88	1 10	1 25	1 40	1 55	1 65	1 90
2 " 4½ " "	22	43	65	90	1 15	1 35						
RING PLATES.												
1 in. pipe, 2½ in. centre to centre	16	28	41	50	62	72	96	1 00				
1½ " 3 " "	21	35	50	62	75	1 10	1 25	1 40				