

CUTTING OF METALS.

Milling Cutters.

Fig. 33.




Fig. 34.



Fig. 35.



Fig. 36.



Fig. 38.



Fig. 40.




Fig. 37.




Fig. 39.

Method of Grinding Cutters.




Fig. 41.




Fig. 42.




Fig. 43.




Fig. 44.



Fig. 45.

