

**Erratum at close of Appendices, Page 87.**

---

The above Statements are compiled from the Division Engineer's returns, and do not include St. Maurice Bridge = 1,500 c. yards.

The above should be:—"The above Statements are compiled from the Division Engineer's returns, and include the St. Maurice Bridge=4,500 c. yards."