

In conclusion I beg to give the present distribution of the Miners.

Sinking Trial Shaft.....	9 men
“ Prideaux Shaft.....	9 “
“ Engine Shaft.....	9 “
“ Meredith Shaft.....	9 “
In the Winze.....	9 “
Driving East, 15 fathoms level from Ferrier Shaft...	4 “
Stopeing in No. 3 East.....	4 “
“ “ 3 West.....	4 “
“ “ 4	3 “
“ “ 5 East..	4 “
“ “ 5 West.....	4 “
“ “ 6	3 “
“ “ 11	4 “
“ “ 15	2 “
“ “ 18 and 19.....	4 “
“ “ 20 and 21.....	4 “

Total..... 85 men.

I have the honor to be,

Sir,

Your most obedient servant,

WALTER WM. PALMER.