

## APPENDIX

## RETURN of the Illuminating Power and Purity of Gas

INSPECTION OFFICE.	Illuminating Power.						Sulphur per		
	Highest.	Lowest.	Average.	Standard.	No. of times be- low Standard.	No. of Tests.	Highest	Lowest.	Average
	Candles.	Candles.	Candles.	Candles.			Grains.	Grains.	Grains.
<b>Ingersol—</b>									
July.....			20·61	16	0	1			
August.....			21·00	16	0	1			
September.....			20·40	16	0	1			
October.....			21·71	16	0	1			
November.....			23·76	16	0	1			
December.....			23·51	16	0	1			
January.....			23·22	16	0	1			
February.....			22·77	16	0	1			
March.....			22·20	16	0	1			
April.....			21·21	16	0	1			
May.....			22·03	16	0	1			
June.....			20·90	16	0	1			
					0	12			
<b>Kingston—</b>									
July.....	23·14	20·11	21·94	16	0	4			
August.....	23·35	20·50	21·91	16	0	4			
September.....	23·41	21·66	22·54	16	0	4			
October.....	24·27	23·73	23·76	16	0	4			
November.....	22·44	20·30	21·30	16	0	4			
December.....	23·09	20·88	22·31	16	0	4			
January.....	23·34	22·18	22·76	16	0	4			
February.....	23·12	22·36	22·66	16	0	3			
March.....	23·39	21·86	22·76	16	0	4			
April.....	23·00	22·13	22·40	16	0	4			
May.....	23·90	21·42	23·01	16	0	4			
June.....	24·40	23·76	23·73	16	0	4			
					0	47			
<b>Lindsay—</b>									
July.....			23·68	16	0	1			
August.....			23·27	16	0	1			
September.....			21·33	16	0	1			
October.....			23·48	16	0	1			
November.....			22·25	16	0	1			
December.....									
January.....			20·62	16	0	1			
February.....			20·17	16	0	1			
March.....			18·22	16	0	1			
April.....			21·10	16	0	1			
May.....			22·75	16	0	1			
June.....			23·68	16	0	1			
					0	11			