



Right way to catch iron. Cutting the stream in towards the furnace.



Wrong way to catch iron. Cutting the stream away from the furnace.