

Other Treatment of the Assembly Room:

Echoes are a fault in auditoriums quite distinct from disturbances caused by too great a period of reverberation. There is a suggestion of echo at the back of the Assembly Room caused by the curved walls in the recess at the back. This condition is not serious but we believe this could be eliminated if necessary by blocking off this recess by means of a partition or heavy curtains.

Summary:

We have found that the period of reverberation of the Assembly Room for frequencies 512 and 1024 is quite satisfactory. For frequency 2048 it is somewhat too short.

We have found that the specifications regarding the period of reverberation to be produced have been fulfilled by the Company which installed the acoustic board.

J. T. DONALD & COMPANY, LTD.

Sgd. (J.R. Macaulay)
Vice-President