



-  Diamond drill hole
-  Open cuts and Test pits
-  Shafts
-  Strippings
-  Pits filled with water
-  Swamps
-  Contours, interval 10 feet  
Elevations above sea level
-  Mine dumps

NO. 190

Surveyed by  
E. Lindeman 1911  
Assisted by O. G. Gallaher