



35252

Gates' Brush.




35254 Earle's Device for Injecting Air and Steam into Furnaces.




35255

Snyder's Toy.




35256


Frick's Stuffing Box.



35257 Mears' Safety Valve Attachments for Cocks.




35258 Burnham's Actuated Valve for Steam Engines.




35261

Lawrence's Pulley Support.



35262

Ford's Automatic Boiler Cleaner.



35263 Lumaghi's Apparatus for the Reduction of Argentiferous Ores.