

ders be solicited for the work of rebuilding the interior in the same manner as the North Wing, with the following exceptions viz:

"The partition walls to be built of brick, but the jambs of the corridor and cell doors must be of cut stone, the windows looking into the gaol yard to be enlarged, the others to remain as they are. The cells need not be arched in brick but roofed with joists and oak plank covered with boiler plate."

"If these suggestions meet with the approval of the Council, sketch plans embodying them could be prepared and submitted to the Inspector for his further recommendations. The expense of carrying out proposed reconstruction, if the prison labour be properly utilized, would not be large, and it would be lessened to the County by the payment of the balance of the \$6000, for gaol repairs to which they would be entitled under the provision of the Inspection Act, when the work was completed.

J. W. LANGMUIR,
Inspector.

