

Fig. 6 shows one of the covered boxes, and Fig. 7 is a photograph of a box containing two switches with the indicator and battery connected ready for taking temperatures, while Figs. 8-11 show the positions of the thermometers in the grain.



Fig. 6. Illustration showing one of the covered boxes.



Fig. 7. Illustration showing box containing two switches.




Fig. 8. Diagram showing arrangement of thermometers in forward hold, those on starboard side being indicated by continuous lines and those on port side by dotted lines.